



Technical Data

Hygrometer

Range:	Humidity:	20% to 100% RH
	Temperature:	0° to 160°F (-18° to 72°C)
Resolution:	Humidity:	2% RH
	Temperature:	0.1°F or C
Accuracy:	Humidity:	±4% FS from 20 to 90% RH ±8% FS from 90 to 100% RH
	Temperature:	±1.8°F (±1°C)
Display:	Humidity:	Analog
	Temperature:	LCD
Power:		One AA 1.5-V battery (included)
Response Time:		90% in 1 minute
Output:		None
Dimensions:		5" dia x 1.1" deep
Shipping Wt:		2 lbs (0.9kg)

Barometer

Air Pressure	Range:	945 to 1045 mbar (black scale); 27.5 to 30.9 in. Hg (red scale)
	Resolution:	0.5 mbar; 0.1 in. Hg
	Accuracy:	± 1mbar; ±0.1 in. Hg
Temperature	Range:	-20° to 60°C (-40° to 140°F)
	Resolution:	0.1°C or F
	Accuracy:	±1°C or 1.8°F
	Power:	One AA battery (included)
	Dimensions:	1.1"D x 5"dia
Shipping Wt:		2 lbs (1kg)