

# AAA Tip Chart

**Replace Your Kremlin™ Tips at an Economical Price**

C.A.Technologies offers a variety of Air Assisted Airless tips to match any users materials and needs for the spray gun industry. All C.A.Technologies Air Assist Airless tips can fit into any Air Assisted Airless Kremlin™ model spray gun.

## AAA Tips

### Feature

- Quality Price and Performance
- C.A.T. Air Assist Airless Tips Can Replace Any Kremlin™ Tip
- Variety of Tip Sizes For All Fine Finish Coatings



98-8007  
Tip O-Ring



36-100-10  
Tip Screen



\*Remove Tip Ring to Replace in Kremlin™ AAA Spray Gun

## Accessories

### 53-591

- 1/4" NPT Female to #5 JIC Male
- Connects Cougar or Bobcat Spray Gun to Kremlin™ Air Assist Airless Fluid Hose



53-591  
1/4" NPS Female  
to #5 JIC Male



53-592  
#5 JIC Female  
to 1/4" NPS Male

### 53-592

- #5 JIC Female to 1/4" NPS Male
- Connects CAT Fluid Hose to Kremlin™ Air Assist Airless Spray Gun and/or Pump

Use for the following combinations:

<u>Spray Gun</u>	<u>Fluid Hose</u>	<u>Pump</u>	<u>QTY 53-591</u>	<u>QTY 53-592</u>
C.A.Technologies	Kremlin™	Kremlin™	(1) 53-591	
C.A.Technologies	Kremlin™	C.A.Technologies	(2) 53-591	
C.A.Technologies	C.A.Technologies	Kremlin™		(1) 53-592
Kremlin™	Kremlin™	C.A.Technologies	(1) 53-591	
Kremlin™	C.A.Technologies	C.A.Technologies		(1) 53-592
Kremlin™	C.A.Technologies	Kremlin™		(2) 53-592

## C.A. Technologies - Kremlin™ Conversion Chart

C.A.T. Part #	Description	Kremlin™ Part #	Spray Angle (degrees)	Pattern Width (inches)	Orifice Size
36-207	AA TIP ASSY. - 207	03-03	20	4	0.007
36-407	AA TIP ASSY. - 407	03-07	50	8	0.007
36-309	AA TIP ASSY. - 309	04-05	30	6	0.009
36-409	AA TIP ASSY. - 409	04-07	40	8	0.009
36-509	AA TIP ASSY. - 509	04-11	50	10	0.009
36-709	AA TIP ASSY. - 709	04-13	70	14	0.009
36-211	AA TIP ASSY. - 211	06-03	20	4	0.011
36-311	AA TIP ASSY. - 311	06-05	30	6	0.011
36-411	AA TIP ASSY. - 411	06-07	40	8	0.011
36-511	AA TIP ASSY. - 511	06-11	50	10	0.011
36-611	AA TIP ASSY. - 611	06-13	60	12	0.011
36-711	AA TIP ASSY. - 711	06-15	70	14	0.011
36-213	AA TIP ASSY. - 213	09-03	20	4	0.013
36-313	AA TIP ASSY. - 313	09-05	30	6	0.013
36-413	AA TIP ASSY. - 413	09-09	40	8	0.013
36-513	AA TIP ASSY. - 513	09-11	50	10	0.013
36-613	AA TIP ASSY. - 613	09-13	60	12	0.013
36-713	AA TIP ASSY. - 713	09-15	70	14	0.013
36-315	AA TIP ASSY. - 315	12-05	30	6	0.015
36-415	AA TIP ASSY. - 415	12-07	40	8	0.015
36-515	AA TIP ASSY. - 515	12-11	50	10	0.015
36-615	AA TIP ASSY. - 615	12-13	60	12	0.015
36-715	AA TIP ASSY. - 715	12-15	70	14	0.015
36-815	AA TIP ASSY. - 815	12-17	80	16	0.015
36-317	AA TIP ASSY. - 317	(18 or 14)-05	30	6	0.017
36-417	AA TIP ASSY. - 417	(18 or 14)-09	40	8	0.017
36-517	AA TIP ASSY. - 517	(18 or 14)-11	50	10	0.017
36-617	AA TIP ASSY. - 617	(18 or 14)-13	60	12	0.017
36-717	AA TIP ASSY. - 717	(18 or 14)-15	67	14	0.017
36-419	AA TIP ASSY. - 419		40	8	0.019
36-619	AA TIP ASSY. - 619		60	12	0.019
36-621	AA TIP ASSY. - 621	20-136	60	12	0.021
36-721	AA TIP ASSY. - 721	20-136	70	14	0.021
36-425	AA TIP ASSY. - 425	20-156	40	8	0.025
36-625	AA TIP ASSY. - 625		60	12	0.025